


JUNE NEWSLETTER CORRECTIONS

The sketch of the 2006 IBC stairway requirements in the June 2006 edition of **CODES & STANDARDS** was in error. Here is the correct code requirement as it should appear. Thanks to our readers for bringing it to our attention...



1 STAIR SECTION
NTS



THE INFO ON the AIA/CES giving 0.50 credit hours for reading **CODES & STANDARDS** seems premature. We are still negotiating with AIA due to the fact that they only recognize credits in 1 hour increments. (Can you read really sloooowww?) More details on this in the future.

CODE QUESTIONS ?

TIME TO CATCH up and answer some of the technical questions from our readers. Here goes...

QUESTION? "When the IPC requires as a drinking fountain, can the faucet from an employee kitchen be an alternative for compliance?"

ANSWER: NO. Neither a kitchen sink faucet or dispenser on a refrigeration meet the standards for drinking fountains.



QUESTION? "Does the 30 ft. spacing of smoke detectors in a fire alarm system required by NFPA No. 72 (Fire Alarm Code) represent the U L listing of the device?"